


Double Check Backflow Preventer



ITEM NO.	DESCRIPTION	QUANTITY	PART NO.
			1/2"
1	Body	1	Consult Factory
2	Cap	2	F-3009-06
3	Spring	2	A-1750-00
4	Poppet	2	K-3404-00
5	Seat Disc	2	D-2600-00
6	Cap O-Ring	2	D-2501-00
7	Test Cock	3	78-257-01
8	Union Nut	1	C-1778-06
9	Tail Piece	1	L-5226-06
10	Seal	1	D-2607-00

Repair Kits

Major Repair Kit

(3 (2), 6 (2), part no. W-6759-06 (2))

40-300-02

Rubber Repair Kit

(5 (2), 6 (2))

40-300-01